




PALHAS FORA DE LINHA


CI - 07/NOV/25

Prezados,

Informamos que, por questões técnicas as palhas TEC019, TEC020, TEC021, TEC022, TEC024, TEC025 estão fora de linha. Elas têm espessura maior do que as demais, o que tem causado problemas na compatibilização com os nossos produtos. Portanto, pedimos que não utilizem mais essas palhas nos projetos, mesmo que ainda estejam disponíveis em sistema. Continuarão disponíveis as palhas TEC014, TEC015, TEC016, TEC023 e TEC026.



FORA DE LINHA



CONTINUAM EM LINHA

Atenciosamente,

Desenvolvimento de Produto



DISCONTINUED STRAWS


CI - 07/NOV/25

Dear all,

We inform that, due to technical issues, the straws TEC019, TEC020, TEC021, TEC022, TEC024, TEC025 have been discontinued. They are thicker than the others, which has caused problems in compatibility with our products. Therefore, we ask that you no longer use these straws in the projects, even if they are still available in the system. TEC014, TEC015, TEC016, TEC023 and TEC026 straws are still available.



DISCONTINUED



STILL AVAILABLE

Best regards,

Product Development